

To Genpo

 May 29th, 2015
 JTEKT CORPORATION
 Aftermarket Sales Dept.

..... Change of Grease

Bearings for Automotive application

Koyo Parts Number	Stock No.	Parts No.	JAN Code
① PU245034BRR1D FGP0/00 <u>K</u> H <u>A</u> ↓ FGP0/00 <u>K</u> 8 <u>A</u>	70107	14520-PFB-003 14520-PZ1-003 14520-PZ1-004	4549250236570
② PU245339ARR1DV FGP0/00K <u>H</u> <u>A</u> ↓ FGP0/00K8 <u>A</u>	70374	14510-P08-003 14510-P08-004 14510-P2A-003 14510-P2A-004 14520-P2A-305	4549250236136
③ PU277027HRR1ZS1 //P0/00 <u>K</u> H <u>A</u> ↓ //P0/00 <u>K</u> 8 <u>A</u>	70114	13404-PCA-003 13404-PT0-003 13404-PT0-004	4549250236037
④ PU285524ARR1D FGP0/00 <u>K</u> H <u>A</u> ↓ FGP0/00 <u>K</u> 8 <u>A</u>	77044	14550-P8A-A01	4549250236044
⑤ PU285530RR1DV1 FGP0/00 <u>K</u> H <u>A</u> ↓ FGP0/00 <u>K</u> 8 <u>A</u>	70382	14510-P30-003 14510-PR3-003 14510-PR3-004	4549250236051
⑥ PU326231GRR1DV FGP0/00 <u>K</u> H <u>A</u> ↓ FGP0/00 <u>K</u> 8 <u>A</u>	77025	5-86000-146 14510-PT0-003 14510-PT0-004	4549250236143

Timing of change	June 2015
Note	Due to change of Grease (KH→K8), JAN Code is also changed.